

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Russell Hardy
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0150007		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, August 19, 2008		
Start Date/Time:	8/19/2008 7:30:00 AM		
End Date/Time:	8/19/2008 1:00:00 PM		
Last Inspection:	Tuesday, July 15, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 70 Deg. F. InspectionID Report Number: 1741

Accepted by: jhelfric

9/2/2008

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Mineral Ownership

Types of Operations

✓ Underground

960.00 Total Permitted **Total Disturbed** 6.70 6.70 Phase I Phase II Phase III

Current Acreages

☐ Federal ☐ State

County Fee

Other

☐ Surface

 □ Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit last renewed 1/29/2007. The permit area is 960 acres within T. 23 S. R. 6 E. W1/2 Sec 17 and all of Sec. 18. The Permittee's address is listed on the Reclamation Agreement [12755 Olive Blvd. St Louis Mo] has changed. The corporate headquarter's address should read [1800 Washington Rd., Pittsburgh PA]. The Engineering Office for the western operations is in Sesser, IL. Consolidation Coal Co. Board of Directors has authorized an exploratory engineering study at the Hidden Valley reclaimed site.

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, August 20, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 19, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		5	No. 6 Amortina bla	0	F
1.	Permits, Change, Transfer, Renewal, Sale	Evaluated	Not Applicable	Comment	Enforcemen
 2.	Signs and Markers	V			
2: 3.	Topsoil				
ن. 4.a	Hydrologic Balance: Diversions	<u> </u>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<u> </u>	<u> </u>		
4.c	Hydrologic Balance: Other Sediment Control Measures	<u> </u>			
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 19, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

Permit last renewed 1/29/2007. The permit area is 960 acres within T. 23 S. R. 6 E. W1/2 Sec 17 and all of Sec. 18. The Permittee's address is listed on the Reclamation Agreement [12755 Olive Blvd. St Louis Mo] has changed. The corporate headquarter's address should read [1800 Washington Rd., Pittsburgh PA]. The Engineering Office for the western operations is in Sesser, IL. Consolidation Coal Co. Board of Directors has authorized an exploratory engineering study at the Hidden Valley reclaimed site.

2. Signs and Markers

The mine ID sign is still in place at the point of public access. The sign conatins the required information, but is fading to the point that it needs maintenance or replacement.